



NO.: HY17DR-1006RN-03

Page 1 of 5

# TEST REPORT

**Client name:** Kavosh Dade Pardazan co.,ltd ( KDT )

**Client address:** Unit 6 - no337 - goleston ST - Narmak - Tehran - Iran

**Sample name:** Dome Camera

**Sample model:** D25

**Sample quantity:** 1PC

**Testing period:** Apr.07, 2017

**Test item:** As specified by client, to do IK10 test on the submitted sample.

**Test method:** EN62262-2002

**Test conclusion:** PASS

Tested by:

*Ngier*  
(Signature)

Inspected by:

*Sigal*  
(Signature)

Approved by:

*Ranzen*  
(Signature)

Shenzhen HuaYao Compliance Testing Laboratory Co., Ltd.

Issued Date: Apr.10, 2017

## Notes:

The test report is responsible to the sample accepted by the laboratory only, The test report is invalid without the stamp of "signature seal of test unit", the modified report is invalid, The part of Copy report is invalid, the test report without the signatures of operator, supervisor and manager is invalid; when there is disagreement to the test report, The test unit should be informed within 10 days since the report is received by the client, Overdue information will not be accepted.